+ COORDINATED OFFICE CLEARANCE


CLEAR THE WORKPLACE. CONNECT THE FIELD SCOPES. ONE ACCOUNTABLE PARTNER.

ASI coordinated office furniture clearance, utility interfaces, exterior sign removal and affected-wall preparation for Dohrmann Insurance in Stockton, California.

CLEAR
FURNITURE

REMOVE
EXTERIOR SIGNS

PREP
AFFECTED WALLS



OVERVIEW

CHALLENGE

The origin-office scope combined movable furnishings, cubicle utility connections, wall-mounted items and exterior signage. These interfaces required coordinated assignments while keeping retained glazing, cabinetry and building finishes in place.

ASI APPROACH

ASI coordinated office furniture clearance, utility interfaces, exterior sign removal and affected-wall preparation for Dohrmann Insurance in Stockton, California.

RESULTS

- Movable furnishings were cleared from the open office area.
- The front exterior sign was removed.
- Affected walls were patched, with fixed elements retained.

DOHRMANN INSURANCE | STOCKTON

At Dohrmann Insurance's Stockton workplace, ASI connected furniture removal with cubicle cable and power-disconnect interfaces, wall preparation and a separate exterior-sign assignment. Field views show a cleared office footprint, removed front signage and visible wall patches, with fixed elements and existing finishes retained.

PROJECT INFO

CLIENT
Dohrmann Insurance

GROUP
Alera Group

LOCATION
Stockton, California

SCOPE
Clearance and sign removal

DELIVERY
Coordinated field scopes

STATUS
Removal and preparation

+ THE COORDINATED SCOPE

INTERIOR CLEARANCE.
EXTERIOR-SIGN REMOVAL.

ASI coordinated the removal and utility interfaces with Metropolitan Van and Storage and the exterior-sign assignment with Tracy Sign. The coordinated scope included furniture dismantling and removal, cubicle cable abatement, base-feed disconnects, wall-item removal and paint-ready patching.



CLEARANCE

FURNITURE AND UTILITY INTERFACES

SIGNAGE

EXTERIOR-SIGN ASSIGNMENT

PREPARATION

PAINT-READY WALL PATCHING

ONE COORDINATED FIELD SCOPE

ASI connected interior clearance, utility interfaces, sign removal and affected-wall preparation through one accountable coordination point.

CLEAR SPACE. PREPARED SURFACES.

Movable furnishings were cleared from the open office area, and the front exterior sign was removed. Wall patching prepared the affected interior surfaces for the next finishing phase, while fixed cabinetry, glazing and existing floor finishes remained in place.

+ FIELD EXECUTION

REMOVE WHAT MOVES.
PROTECT WHAT STAYS.

Wall-mounted items were removed and affected surfaces patched beside retained glass doors and fixed cabinetry. Existing floor finishes remained in place as the walls were prepared for the next finishing phase.



IN PROGRESS: CORRIDOR WALL PREPARATION AFTER REMOVAL OF WALL-MOUNTED ITEMS. PATCHES REMAIN VISIBLE.



IN PROGRESS: AFFECTED-WALL PREPARATION BESIDE RETAINED FIXED CABINETRY. PATCHES AND EXISTING FINISHES REMAIN.

ONE ACCOUNTABLE COORDINATION POINT

ASI connected interior clearance, utility interfaces, sign removal and affected-wall preparation through one accountable coordination point. Planning an office clearance with multiple field scopes? Talk with ASI about one accountable coordination point.