+ A HIGH-RISE WORKPLACE EXIT. CONNECTED SCOPES.

BEYOND THE FURNITURE.

INTO THE CONNECTIONS.

ASI coordinated office dismantling, cable removal and localized wall repairs for Zenith through Re:Sources in Century City.

FURNITURE. CABLING. TRANSPORT. WALL REPAIR.



OVERVIEW

CHALLENGE

A high-rise office exit involved furniture, workplace connections and wall-mounted items. Building logistics and changing haul arrangements added coordination beyond dismantling.

ASI APPROACH

ASI brought installers, technical removal and material handling into one coordinated assignment, then addressed selected office attachment points through local wall patching.

RESULTS

- Workplace cabling removed
- Selected offices cleared
- Local wall attachment points patched

ZENITH | LOS ANGELES

The removal extended into the systems and surfaces behind the furniture. ASI connected the dismantling and cable-removal work with transport coordination and localized repairs in cleared offices.

PROJECT INFO

CLIENT
Zenith

LOCATION
Los Angeles, California

SITE
2049 Century Park East

WORKPLACE
13th floor

SCOPE
Technical decommission

DELIVERY
Through Re:Sources


+ TECHNICAL SCOPE

FOLLOW THE CONNECTIONS.
COORDINATE THE REMOVAL.

The cable paths were part of the exit, too. These original field views show removal in progress, with ceiling access, tools and material handling still active.



WORKPLACE CABLE REMOVAL | IN PROGRESS



SERVER-ROOM CABLE REMOVAL | IN PROGRESS

THE TECHNICAL LAYER

Data cabling ran through the workplace and into the server-room pathways. Removal involved more than disconnecting visible furniture.

THE HANDLING LAYER

The haul arrangements changed as the job developed. ASI connected the removal crews with loading support and the transport plan.

+ THE ASI DELIVERY MODEL

THE EXIT REACHED BEYOND
WHAT WAS ON THE FLOOR.

Furniture, cabling and wall attachments called for different skills. ASI coordinated those responsibilities while adapting the haul plan to the building and the work underway.

CLEAR

DISMANTLE THE WORKPLACE

Installer teams carried out office removal work. Workstations, private offices, meeting areas and supporting spaces formed the coordinated assignment.

CABLE

REMOVE WORKPLACE DATA CABLING

Cable removal extended from office areas into the server-room pathways. Field views show bundles being removed and collected for handling.

POWER

COORDINATE THE DISCONNECTS

The agreed scope assigned the electrical connections serving tables, cubicles and conference furniture to an electrician alongside the dismantling work.

HAUL

ADAPT THE TRANSPORT PLAN

The field plan changed from containers to a transport arrangement with ASI loading support, keeping material handling aligned with building constraints.

PATCH

REPAIR LOCAL ATTACHMENT POINTS

Later cleared-office views show localized wall patching where mounted items had been removed. Existing carpet and surrounding finishes remained.

PROJECT INFO

CLIENT
Zenith

LOCATION
Los Angeles, California

SITE
2049 Century Park East

FLOOR
13

COORDINATION
Re:Sources

FOCUS
Removal and repair

STATUS
COMPLETED SCOPES

FURNITURE, CABLING AND LOCAL REPAIRS

Office dismantling and cable removal were coordinated with the haul arrangements. Selected rooms then received localized patching at the removal points, retaining existing finishes.

DISMANTLE | DISCONNECT | REMOVE | HANDLE | CLEAR | PATCH

ONE ACCOUNTABLE PARTNER FOR THE PHYSICAL AND TECHNICAL WORKPLACE EXIT.

+ THE OUTCOME

REMOVAL WITH TECHNICAL FOLLOW-THROUGH.

The field work addressed both office contents and their supporting connections. Later room views show cleared spaces and local wall patches after the removal work.

REMOVE

WORKPLACE CABLING

Field crews removed and gathered the data cabling.

CLEAR

SELECTED OFFICES

Later photographs show offices cleared of their contents.

PATCH

LOCAL WALL REPAIRS

Attachment points received localized wall patching.

WHAT THE PROJECT DELIVERED

CONNECTED RESPONSIBILITIES

Furniture removal and its electrical, low-voltage and handling requirements sat within one coordinated assignment.

TECHNICAL WORK MADE VISIBLE

Action views show cable bundles in removal and material collected for handling.

LOCAL REPAIR AFTER REMOVAL

Cleared offices show patches at the former wall attachment points.

EXISTING FINISHES RETAINED

The documented local repairs retained the surrounding carpet, walls and ceiling finishes.

ONE ACCOUNTABLE PARTNER. REMOVAL. COORDINATION. LOCAL REPAIR.

DELIVERY RESULT

ASI connected the installation crews, technical removal, transport arrangements and local repair work involved in this high-rise office exit.

PLANNING A COMPLEX WORKPLACE EXIT?

ASICOINC.COM | PROJECTS@ASICOINC.COM

+ SELECTED OFFICE REPAIRS

CLEARED ROOMS.
LOCALIZED WALL REPAIRS.

Later photographs show the local repair phase in selected offices. Patches at former attachment points remain visible, with existing carpet and surrounding finishes retained.



LOCAL WALL PATCHING | COMPLETED



CLEARED OFFICE AND PATCHED ATTACHMENT POINTS | COMPLETED