
+ TARGETED MEETING-ROOM WALL REPAINT

DEFINED SCOPE.
WALL REPAINT.
DOCUMENTED CLOSEOUT.

ASI coordinated a targeted meeting-room wall repaint through GWS Partners, defining the finish boundary and bringing field execution and closeout into one accountable path.

WALL	EDGE	FIELD
FULL REPAINT	DEFINED LIMIT	CLOSEOUT



MEETING-ROOM WALL REPAINT COMPLETED

OVERVIEW

CHALLENGE

The repaint called for a complete logical wall termination, not isolated spot painting. The work boundary met adjoining painted surfaces and a glazed doorway, making preparation, protection and clean cut lines important parts of the assigned scope.

ASI APPROACH

ASI brought the approved repaint requirements, field crew coordination and closeout record together. The assigned scope included normal surface preparation, protection of adjacent finishes and repainting the complete approved wall in the specified black finish.

RESULTS

- Approved full-wall black repaint completed.
- Field walkthrough documented.
- Completed wall photographed.

MICROSOFT | VANCOUVER

The Vancouver workplace needed a targeted finish correction at a meeting-room entry. ASI coordinated the approved full-wall black repaint through GWS Partners, keeping the return work focused on the affected surface rather than expanding it into a broader renovation.

PROJECT INFO

CLIENT Microsoft	LOCATION Vancouver, British Columbia
CHANNEL GWS Partners	SCOPE Wall-finish repaint
DELIVERY Targeted return work	STATUS Bounded repaint completed

+ THE OUTCOME

ONE DEFINED WALL REPAINT.
DOCUMENTED FIELD CLOSEOUT.

The approved black-wall repaint was completed. The closeout record included a field walkthrough and photographs of the repainted wall beside the meeting-room entry.

WALL

BOUNDED REPAINT

The approved black-wall scope was completed.

ENTRY

DEFINED WORK BOUNDARY

Adjoining surfaces and the glazed doorway shaped the assigned repaint scope.

FIELD

DOCUMENTED CLOSEOUT

The closeout record included a walkthrough and photographs.

WHAT THE PROJECT DELIVERED

FULL-WALL REPAINT

The approved wall was repainted in the specified black finish.

DEFINED FINISH BOUNDARY

The assigned repaint ran to the complete logical wall termination, not isolated spots.

COORDINATED RETURN WORK

ASI brought the approved repaint requirements, field crew coordination and closeout record together.

CLOSEOUT RECORD

A field walkthrough and photographs documented the bounded black-wall repaint.

ONE ACCOUNTABLE PARTNER.
DEFINED SCOPE. DOCUMENTED CLOSEOUT.

DELIVERY RESULT

ASI kept a corrective finish assignment tied to a defined work boundary and a documented closeout path.

COORDINATE YOUR NEXT WORKPLACE FINISH PROJECT.

ASICOINC.COM | PROJECTS@ASICOINC.COM