+ ONE CONNECTED WORKPLACE EXIT

DISMANTLE THE OFFICE. REMOVE THE CONNECTIONS. CLEAR THE WORKPLACE.

ASI connected furniture teardown, technical removals and building access coordination for Hanley Wood's sixth-floor Los Angeles office exit.

SIXTH-FLOOR OFFICE CLEARANCE. TECHNICAL REMOVALS.



OVERVIEW

CHALLENGE

Furniture could leave the building only after 6 p.m. Workstation teardown, technical cabling and material handling had to fit that access rule while moving contents from a sixth-floor suite to the trucks.

ASI APPROACH

ASI organized the removal sequence around the evening access window and coordinated the interior crews, designated carts, floor protection and truck responsibilities. Cable removal remained part of the same assignment.

RESULTS

- Workstation and office furniture removed
- Technical cable-removal work carried out
- Open office areas and rooms cleared

HANLEY WOOD | LOS ANGELES

The workplace exit reached beyond furniture hauling. ASI connected office teardown and technical removals with the requirement to remove furniture after 6 p.m. and the handling route between the sixth-floor suite and the trucks.

PROJECT INFO

CLIENT
Hanley Wood

LOCATION
Los Angeles, CA

SITE
6222 Wilshire Blvd

WORKPLACE
Suite 600


DELIVERY
Office decommission

STATUS
Clearance completed

+ WORKPLACE SCOPE

A WORKPLACE EXIT
REACHED BEYOND THE FURNITURE.

Workstations, storage and technical cabling occupied the same suite. The field plan connected interior teardown with designated carts, floor protection and truck staging under a restricted furniture-removal window.



OFFICE CABLE REMOVAL AND MATERIAL HANDLING | IN PROGRESS

FURNITURE

DISMANTLE AND REMOVE

TECHNICAL

REMOVE DESIGNATED CABLING

CLEARANCE

REVEAL THE EXISTING INTERIOR

FROM THE SUITE TO THE TRUCK

ASI coordinated the interior work with the loading operation. The field plan assigned carts and Masonite protection, separated truck responsibilities and held furniture removal until the building's evening window.

DEFINED REMOVAL BOUNDARIES

The exit cleared office contents while retaining the existing interior. Walls, ceilings, fixed cabinetry and carpet remain visible in the completed clearance views.

+ THE ASI DELIVERY MODEL

FURNITURE AND INFRASTRUCTURE.
ONE CONNECTED EXIT.

ASI connected the suite work, technical removals and loading operation. The removal plan respected the building's evening removal restriction and assigned clear handling responsibilities.

PLAN

WORK AROUND BUILDING ACCESS

Furniture removal was permitted only after 6 p.m. ASI planned suite teardown around that evening window and scheduled power disconnection and cable removal as a connected follow-on phase.

STRIP

DISMANTLE AND STAGE THE FURNITURE

Crews broke down workstation components. The handling plan connected designated carts, Masonite protection and separate truck responsibilities to move contents out of the sixth-floor suite.

CABLE

ADDRESS THE TECHNICAL REMOVALS

Cable-removal work extended through office areas and the technical room, with removed bundles collected for handling.

REMOVE

CLEAR THE OCCUPIED FOOTPRINT

Furniture and contents were removed from open work areas and private rooms, revealing the existing interior.

RETAIN

KEEP THE BUILDING ELEMENTS DISTINCT

Existing walls, ceilings, fixed cabinetry and floor finishes remained separate from the office contents being removed.

PROJECT INFO

CLIENT
Hanley Wood

LOCATION
Los Angeles, California

SITE
6222 Wilshire Boulevard

SUITE
600

SCOPE
Workplace decommission

DELIVERY
Connected removals

STATUS
CLEARANCE COMPLETED

ONE TEAM CONNECTED THE FIELD INTERFACES

The building access rule affected how work moved from desks and cabling to carts and trucks. ASI coordinated the interior and loading responsibilities as one workplace exit, with furniture removal restricted to the evening window.

PLAN	DISMANTLE	STAGE	DISCONNECT	REMOVE	CLEAR

ONE ACCOUNTABLE PARTNER FOR CONNECTED WORKPLACE-EXIT RESPONSIBILITIES.

+ THE OUTCOME

FROM FURNISHED WORK AREAS TO CLEARED OFFICE INTERIORS.

The office was cleared of its furniture and workstation systems. The field sequence also records cable-removal work, while completed clearance views show the existing rooms and finishes retained.

FURNITURE

WORK AREAS CLEARED

Workstation systems and office contents were removed from the occupied footprint.

TECHNICAL

CABLE REMOVAL

Removed cable bundles and technical-room work form a visible part of the field sequence.

INTERIOR

EXISTING FINISHES RETAINED

The cleared space retained the walls, ceiling, cabinetry and carpet.

WHAT THE PROJECT DELIVERED

BEYOND FURNITURE HAULING

The assignment connected office contents with the technical removals behind the workplace.

CLEAR ROOM CONDITIONS

Broad field views show cleared open areas and private rooms after furniture removal.

ACCESS AND HANDLING COORDINATED

The field plan tied the building's evening removal window to designated carts, floor protection and truck responsibilities.

A VISIBLE FIELD SEQUENCE

Original views show workstations in place, crews dismantling components and the cleared interior.

ONE ACCOUNTABLE PARTNER. FURNITURE. TECHNICAL REMOVALS. CLEARANCE.

DELIVERY RESULT

ASI gave the workplace team one accountable partner for the connected removal assignment, coordinating the building access constraint, hands-on teardown, technical removals and material handling.

PLANNING A WORKPLACE DECOMMISSION?

ASICOINC.COM | PROJECTS@ASICOINC.COM

+ FIELD EXECUTION

REAL FIELD WORK.
A CLEAR CHANGE IN THE SPACE.

The field sequence follows the work from furnished offices through active removal to cleared interiors. Existing carpet, walls and fixed cabinetry remain visible.




WORKSTATION REMOVAL | IN PROGRESS



OFFICE CLEARANCE | COMPLETED



WORKSTATION AREA | BEFORE



CABLE REMOVAL | IN PROGRESS



PRIVATE-OFFICE CLEARANCE | COMPLETED

THE WORKPLACE EXIT INCLUDED THE CONNECTIONS.

Furniture removal and technical strip-out were connected parts of the assignment. The cleared views show the result of the removals, with existing building finishes retained.